

**Jon A. Franke**  
Site Vice President

**PPL Susquehanna, LLC**  
769 Salem Boulevard  
Berwick, PA 18603  
Tel. 570.542.2904 Fax 570.542.1504  
jfranke@pplweb.com



**DEC 31 2014**

U. S. Nuclear Regulatory Commission  
Attn: Document Control Desk  
Washington, DC 20555-0001

**SUSQUEHANNA STEAM ELECTRIC STATION  
LICENSEE EVENT REPORT 50-388(387)/2014-001-00  
UNIT 1 LICENSE NO. NPF-14  
UNIT 2 LICENSE NO. NPF-22  
PLA-7270**

---

**Docket Nos. 50-387  
and 50-388**

Attached is Licensee Event Report (LER) 50-388(387)/2014-001-00. The LER reports an event involving both doors of a secondary containment airlock being momentarily open resulting in a condition that met the reporting criterion for a condition that could have prevented fulfillment of a safety function.

There were no actual consequences to the health and safety of the public as a result of this event.


This letter contains no new regulatory commitments.

 For J. A. Franke  
J. A. Franke

Attachment: LER 388(387)/2014-001-00

Copy: NRC Region I  
Mr. J. E. Greives, NRC Sr. Resident Inspector  
Mr. J. A. Whited, NRC Project Manager  
Mr. L. J. Winker, PA DEP/BRP

IE22  
NRR

NRC FORM 366 (02-2014)		U.S. NUCLEAR REGULATORY COMMISSION			APPROVED BY OMB: NO. 3150-0104		EXPIRES: 01/31/2017			
		<b>LICENSEE EVENT REPORT (LER)</b> (See Page 2 for required number of digits/characters for each block)								
1. FACILITY NAME Susquehanna Steam Electric Station, Unit 2					2. DOCKET NUMBER 05000388		3. PAGE 1 of 3			
4. TITLE Both Doors of a Secondary Containment Personnel Airlock Momentarily Open Due to a Personnel Error Resulting in Entry into Secondary Containment Technical Specification Limiting Condition for Operation										
5. EVENT DATE			6. LER NUMBER			7. REPORT DATE			8. OTHER FACILITIES INVOLVED	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REV NO.	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER
11	05	2014	2014	- 001	00	12	31	2014	Susquehanna Steam Electric Station, Unit 1	05000387
									FACILITY NAME	DOCKET NUMBER
										05000
9. OPERATING MODE		11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check all that apply)								
10. POWER LEVEL  100		<input type="checkbox"/> 20.2201(b)		<input type="checkbox"/> 20.2203(a)(3)(i)		<input type="checkbox"/> 50.73(a)(2)(i)(C)		<input type="checkbox"/> 50.73(a)(2)(vii)		
		<input type="checkbox"/> 20.2201(d)		<input type="checkbox"/> 20.2203(a)(3)(ii)		<input type="checkbox"/> 50.73(a)(2)(ii)(A)		<input type="checkbox"/> 50.73(a)(2)(viii)(A)		
		<input type="checkbox"/> 20.2203(a)(1)		<input type="checkbox"/> 20.2203(a)(4)		<input type="checkbox"/> 50.73(a)(2)(ii)(B)		<input type="checkbox"/> 50.73(a)(2)(viii)(B)		
		<input type="checkbox"/> 20.2203(a)(2)(i)		<input type="checkbox"/> 50.36(c)(1)(i)(A)		<input type="checkbox"/> 50.73(a)(2)(iii)		<input type="checkbox"/> 50.73(a)(2)(ix)(A)		
		<input type="checkbox"/> 20.2203(a)(2)(ii)		<input type="checkbox"/> 50.36(c)(1)(ii)(A)		<input type="checkbox"/> 50.73(a)(2)(iv)(A)		<input type="checkbox"/> 50.73(a)(2)(x)		
		<input type="checkbox"/> 20.2203(a)(2)(iii)		<input type="checkbox"/> 50.36(c)(2)		<input type="checkbox"/> 50.73(a)(2)(v)(A)		<input type="checkbox"/> 73.71(a)(4)		
		<input type="checkbox"/> 20.2203(a)(2)(iv)		<input type="checkbox"/> 50.46(a)(3)(ii)		<input type="checkbox"/> 50.73(a)(2)(v)(B)		<input type="checkbox"/> 73.71(a)(5)		
		<input type="checkbox"/> 20.2203(a)(2)(v)		<input type="checkbox"/> 50.73(a)(2)(i)(A)		<input checked="" type="checkbox"/> 50.73(a)(2)(v)(C)		<input type="checkbox"/> OTHER		
<input type="checkbox"/> 20.2203(a)(2)(vi)		<input type="checkbox"/> 50.73(a)(2)(i)(B)		<input type="checkbox"/> 50.73(a)(2)(v)(D)		Specify in Abstract below or in NRC Form 366A				
12. LICENSEE CONTACT FOR THIS LER										
LICENSEE CONTACT C. E. Manges, Jr., Senior Engineer – Nuclear Regulatory Affairs								TELEPHONE NUMBER (Include Area Code) 570 542 3089		
13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT										
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX	
14. SUPPLEMENTAL REPORT EXPECTED						15. EXPECTED SUBMISSION DATE				
<input type="checkbox"/> YES (If yes, complete 15. EXPECTED SUBMISSION DATE)						<input checked="" type="checkbox"/> NO				
						MONTH		DAY	YEAR	
ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)										
<p>On November 5, 2014 at 1115 hours, Secondary Containment Zone 3 (Unit 1 &amp; 2 Reactor Building) was unintentionally cross tied to Secondary Containment Zone 2 (Unit 2 Reactor Building) for several seconds during passage of personnel through a personnel airlock. Secondary Containment Zone 2 and Zone 3 ventilation remained in service and stable. Limiting Condition for Operation (LCO) 3.6.4.1 was entered and exited based on the prohibited crosstie of Secondary Containment Zones. This event was reported under 10 CFR 50.72(b)(3)(v)(C) as a loss of a safety function. There is no redundant Susquehanna Secondary Containment System.</p> <p>The cause of the event was a human performance error in that a self-check was not performed prior to opening the airlock door. The individual was coached on the importance of self-check for verifying conditions are met prior to passage through a Secondary Containment airlock door. A communication to all station personnel will be distributed reinforcing the significance of secondary containment airlocks, the conditions required for passage through an airlock, and how to verify these conditions.</p> <p>There were no actual consequences to the health and safety of the public as a result of this event.</p>										

**LICENSEE EVENT REPORT (LER)  
CONTINUATION SHEET**

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Privacy and Information Collections Branch (T-5 F53), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to [Infocollects.Resource@nrc.gov](mailto:Infocollects.Resource@nrc.gov), and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
Susquehanna Steam Electric Station, Unit 2	05000388	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	2 of 3
		2014	- 001	- 00	

**NARRATIVE****CONDITIONS PRIOR TO EVENT**

Unit 1 – Mode 1, 100 percent Rated Thermal Power

Unit 2 – Mode 1, 100 percent Rated Thermal Power

There were no structures, systems, or components that were inoperable at the start of the event that contributed to the event.

**EVENT DESCRIPTION**

On November 5, 2014 at 1115 hours, Secondary Containment Zone 3 (Unit 1 & 2 Reactor Building [EIS System Identifier: NG]) was unintentionally cross tied to Secondary Containment Zone 2 (Unit 2 Reactor Building) for approximately two seconds during passage of personnel through a personnel airlock [EIS Component Identifier: AL]. Secondary Containment Zone 2 and Zone 3 ventilation [EIS System Identifier: VA] remained in service and stable.

Limiting Condition for Operation (LCO) 3.6.4.1 was entered and exited based on the prohibited crosstie of Secondary Containment Zones. Technical Specification Secondary Containment Operability requires that at least one door [EIS Component Identifier: DR] remain closed for airlocks where two doors are provided when an access opening between Secondary Containment Zones is being used for exit and entry.

This event was reported under 10 CFR 50.72(b)(3)(v)(C) and per the guidance of NUREG 1022, Revision 3, Section 3.2.7 as a loss of a safety function (EN 50595). There is no redundant Susquehanna Secondary Containment System.

Details of the investigation of the event are as follows:

A Non-Licensed Operator (NLO) was performing equipment checks in the Unit 2 Reactor Building. Following completion of the equipment checks, the NLO approached Door DR-115R to egress through Airlock II-606. The NLO unlatched Door DR-115R prior to verifying the airlock was clear and that conditions were met for opening the door. During an interview, the NLO stated that at the moment he unlatched the door, he noticed the red light [EIS Component Identifier: IL] was illuminated, indicating the opposite airlock door was not latched and conditions were not met for passage through Door DR-115R. The NLO immediately reclosed and latched Door DR-115R, restoring the airlock and separation of Secondary Containment Zones 2 and 3. After reclosing and latching Door DR-115R, the NLO confirmed that personnel passed through the airlock and had not yet closed and latched the opposite door at the time he unlatched door DR-115R. The NLO immediately notified the Control Room and submitted a condition report to document the event.

The NLO stated that he did not focus on verifying airlock conditions prior to unlatching Door DR-115R.

(02-2014)

**LICENSEE EVENT REPORT (LER)  
CONTINUATION SHEET**

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Susquehanna Steam Electric Station, Unit 2	05000388	2014	- 001	- 00	3 of 3

**NARRATIVE****CAUSE OF EVENT**

The cause of the event was human performance error in that a self-check was not performed prior to opening the airlock door.

**ANALYSIS/SAFETY SIGNIFICANCE**

The actual consequence was inadvertent, prohibited crosstie of Secondary Containment Zones 2 and 3 requiring momentary entry into LCO 3.6.4.1 and an eight hour notification of the event to the Nuclear Regulatory Commission (NRC).

An engineering evaluation was performed and concluded that secondary containment could have performed its safety function of isolating as assumed in the accident analysis and also of re-establishing 0.25 inches vacuum (drawdown) within the assumed accident analysis time (10 minutes). Therefore, the subject event did not cause a loss of safety function. This event will not be counted as a safety system functional failure (SSFF) for the NRC performance indicator based on the engineering analysis that shows there was no loss of ability to fulfill the safety function.

**CORRECTIVE ACTIONS**

The on-shift Shift Manager coached the NLO on the importance of self-check for verifying conditions are met prior to passage through a Secondary Containment airlock door.

A communication to all station personnel will be distributed reinforcing the significance of secondary containment airlocks, the conditions required for passage through an airlock, and how to verify these conditions. The communication will also highlight the need for personnel to verify that the opposite door is closed first and, if possible, locked in position before entering or exiting a personnel airlock (PAL).

**PREVIOUS SIMILAR EVENTS**

No previous similar events were identified.